



REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

Lifting Operations and Lifting
Equipment Regulations 1998
(Regulation 9)

**REPORT NUMBER
L20230324-01**

Employer (and/or plant owner)

HEULWEN TRUSTEES

Address

Cadwallader & Co, Eagle House, 25 Severn st, WELSHPOOL, Powys SY21 7AD

Responsible person

Peter Edwards

Address at which examination was made.

HEULWEN TRUST WARF, WELSHPOOL, POWYS. SY21 9HW

Description of lifting equipment

Electro Hydraulic Disabled person scissor lift on vessel 518785

Distinguishing Number

Not marked

Manufacturers name

Not visible

Year of manufacture

Not marked

Safe working load

1000 kg

Nature of Examination

Thorough examination conducted within an interval of 6 months under Regulation 9(3)(a)(i) unless otherwise stated.

Serious defect which could become an immediate source of danger to persons.

NONE

Other defects

NONE

Observations and conditions of ropes/chains and use etc

There is no handrail on the stern side of the lift. The unusual position and mode of operation of the lift is such that it is not practicable to provide a full wrap around handrail and toe guards would introduce a trip hazard. The lift operator must stand on the unguarded side of the lift in order to keep close control of the passengers. Extreme care should be taken by the operator to avoid waiting passengers from being near the lift whilst in operation. No ropes nor chains fitted. Safety edges operational.

Date of last thorough Examination

29th April 2022

Latest date at which next Thorough Examination must be conducted.

24th Sept 2023

Date of Examination

24th March 2023

Report Date

18th April 2023

Further note.

Design not checked, this report should be read in conjunction with an EC Declaration of Conformity Certificate and/or Initial Thorough Examination Report (inc. load test, where applicable issued by your manufacturer or installer)

Unless otherwise stated this inspection has been completed in accordance with Regulation 9 of Lifting Operations and Lifting Equipment Regulations (LOLER) 1998. I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate.

Signature

Mr P J Langdon MIET Engineering Surveyor
LG Inspections (Midlands) Ltd. 6 St Catherine's Drive. SHREWSBURY, SY3 6AR