



# REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

Lifting Operations and Lifting  
Equipment Regulations 1998  
(Regulation 9)

**REPORT NUMBER  
L20220426-01**

*Employer (and/or plant owner)* **HEULWEN TRUST**

*Address* **Brynithon, Llanbister, LLANDRINDOD WELLS. LD1 6TR**

*Responsible person* **James Grieve**

*Address at which examination was made.* **HEULWEN TRUST WARF, WELSHPOOL, POWYS. SY21 9HW**

*Description of lifting equipment* **Electro Hydraulic Disabled person scissor lift on vessel 71616**

*Distinguishing Number* **Not marked**

*Manufacturers name* **Edmo Lift**

*Year of manufacture* **Not marked**

*Safe working load* **1000 kg**

*Nature of Examination* **Thorough examination conducted within an interval of 6 months under Regulation 9(3)(a)(i) unless otherwise stated.**

*Serious defect which could become an immediate source of danger to persons.* **NONE**

*Other defects* **There is no handrail on the bow side of the lift. Hinged handrails should be provided to avoid the possibility of persons falling off the platform. It should also be noted that where scissor lifts are operated and where guarding of the underside of the lift is not practicable. Extreme care should be taken by the operator to avoid persons being trapped below the lift.**

*Observations and conditions of ropes/chains etc* **No ropes nor chains fitted.**

*Date of last thorough Examination* **1<sup>st</sup> June 2021**

*Latest date at which next Thorough Examination must be conducted.* **26<sup>th</sup> Oct 2022**

*Date of Examination* **26<sup>th</sup> April 2022**

*Report Date* **29<sup>th</sup> April 2022**

*Further note.*

**Design not checked, this report should be read in conjunction with an EC Declaration of Conformity Certificate and/or Initial Thorough Examination Report (inc. load test, where applicable issued by your manufacturer or installer)**

Unless otherwise stated this inspection has been completed in accordance with Regulation 9 of Lifting Operations and Lifting Equipment Regulations (LOLER) 1998. I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate.

Signature

Mr P J Langdon MIET Engineering Surveyor  
LG Inspections (Midlands) Ltd. 6 St Catherine's Drive. SHREWSBURY, SY3 6AR