



REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

Lifting Operations and Lifting
Equipment Regulations 1998
(Regulation 9)

REPORT NUMBER
L20220426-02

Employer (and/or plant owner)

HEULWEN TRUST

Address

Brynithon, Llanbister, LLANDRINDOD WELLS. LD1 6TR

Responsible person

James Grieve

Address at which examination was made.

HEULWEN TRUST WARF, WELSHPOOL, POWYS. SY21 9HW

Description of lifting equipment

Electro Hydraulic Disabled person scissor lift on vessel 518785

Distinguishing Number

Not marked

Manufacturers name

Not visible

Year of manufacture

Not marked

Safe working load

1000 kg

Nature of Examination

Thorough examination conducted within an interval of 6 months under Regulation 9(3)(a)(i) unless otherwise stated.

Serious defect which could become an immediate source of danger to persons.

NONE

Other defects

There is no handrail on the stern side of the lift. A hinged handrail should be provided to avoid the possibility of persons falling off the platform. It should also be noted that where scissor lifts are operated and where guarding of the underside of the lift is not practicable. Extreme care should be taken by the operator to avoid persons being trapped below the lift.

Observations and conditions of ropes/chains etc

No ropes nor chains fitted.

Date of last thorough Examination

1st June 2021

Latest date at which next Thorough Examination must be conducted.

26th Oct 2022

Date of Examination

26th April 2022

Report Date

29th April 2022

Further note.

Design not checked, this report should be read in conjunction with an EC Declaration of Conformity Certificate and/or Initial Thorough Examination Report (inc. load test, where applicable issued by your manufacturer or installer)

Unless otherwise stated this inspection has been completed in accordance with Regulation 9 of Lifting Operations and Lifting Equipment Regulations (LOLER) 1998. I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate.

Signature

Mr P J Langdon MIET Engineering Surveyor
LG Inspections (Midlands) Ltd. 6 St Catherine's Drive. SHREWSBURY, SY3 6AR